


NOTES:

- 1. PINS MUST BE FLUXED PRIOR TO SOLDERING.
- 2. SOLDER SHALL BE 60/40, TIN/LEAD.
- 3. SOLDER JOINTS SHALL BE SMOOTH.
- 4. CABLE CLAMP MUST FULLY GRIP THE DUTER JACKET.
- 5. EXPOSURE OF BARE WIRE SHALL BE MINIMAL.
- 6. INSERT AND WIRE INSULATORS SHALL BE FREE OF BURN MARKS.
- 7. CABLE ASSEMBLIES SHALL BE CDILED AND PACKAGED IN BAGS.



WIRING SCHEMATIC SCALE: 2/1

SR SENIOR INDUSTRIES, INC.	TITLE:	MIDI	CABLE		PART NO: SI-3	46-X	
	DATE:	03/23/95	DRAWN: GAM	CHKD:	SCALE: 1/1	SHEET: 1 OF	1